



Power selection.
It's sufficient to use 9V power supply for 5V fan.
Voltage above 9V will be transformed into heat.

Fan	Power	Jumper W1	Jumper W2
5V	9V	closed	opened
12V	12V	opened	closed

Title PIC laser spirograph. Control board.		
Size A	Number	Revision 1.2
Date:	3/13/2010	Sheet of
File:	C:\projects\pmls_board_1_2.SchDoc	Drawn By: